calculatoratoz.com

unitsconverters.com

Power System Stability Formulas

Calculators! Examples! Conversions!

Bookmark **calculatoratoz.com**, **unitsconverters.com**

Widest Coverage of Calculators and Growing - **30,000+ Calculators!**
Calculate With a Different Unit for Each Variable - **In built Unit Conversion!**
Widest Collection of Measurements and Units - **250+ Measurements!**

Feel free to SHARE this document with your friends!

Please leave your feedback here...

List of 20 Power System Stability Formulas

Power System Stability

1) Accelerating Torque of Generator under Power System Stability

Open Calculator

fx $$T_a = T_m - T_e$$

ex $$32\text{N*m} = 44\text{N*m} - 12\text{N*m}$$

2) Active Power by Infinite Bus

Open Calculator

fx $$P_{inf} = \frac{(V)^2}{\sqrt{(R)^2 + (X_s)^2}} - \frac{(V)^2}{(R)^2 + (X_s)^2}$$

ex $$2.084176\text{W} = \frac{(11\text{V})^2}{\sqrt{(2.1\Omega)^2 + (57\Omega)^2}} - \frac{(11\text{V})^2}{(2.1\Omega)^2 + (57\Omega)^2}$$

3) Angular Displacement of Machine under Power System Stability

Open Calculator

fx $$\delta_a = \theta_m - \omega_s \cdot t$$

ex $$20.2\text{rad} = 109\text{rad} - 8\text{m/s} \cdot 11.1\text{s}$$

4) Clearing Angle

Open Calculator

fx $$\delta_c = \frac{\pi \cdot f \cdot P_i}{2 \cdot H} \cdot (t_c)^2 + \delta_o$$

ex $$61.93019\text{rad} = \frac{\pi \cdot 56\text{Hz} \cdot 200\text{W}}{2 \cdot 39\text{kg·m}^2} \cdot (0.37\text{s})^2 + 10^\circ$$

5) Clearing Time

Open Calculator

fx $$t_c = \sqrt{\frac{2 \cdot H \cdot (\delta_c - \delta_o)}{\pi \cdot f \cdot P_i}}$$

ex $$0.36991\text{s} = \sqrt{\frac{2 \cdot 39\text{kg·m}^2 \cdot (61.9\text{rad} - 10^\circ)}{\pi \cdot 56\text{Hz} \cdot 200\text{W}}}$$

6) Complex Power of Generator under Power Angle Curve

Open Calculator

fx $$S = V_p \cdot I_p$$

ex $$1282.42\text{VA} = 74\text{V} \cdot 17.33\text{A}$$

7) Critical Clearing Angle under Power System Stability

Open Calculator

fx $$\delta_{cc} = a\cos\left(\cos(\delta_{max}) + \left(\frac{P_i}{P_{max}}\right) \cdot (\delta_{max} - \delta_o)\right)$$

ex $$47.58211^\circ = a\cos\left(\cos(60^\circ) + \left(\frac{200\text{W}}{1000\text{W}}\right) \cdot (60^\circ - 10^\circ)\right)$$

8) Critical Clearing Time under Power System Stability

Open Calculator

fx $$t_{cc} = \sqrt{\frac{2 \cdot H \cdot (\delta_{cc} - \delta_{o})}{\pi \cdot f \cdot P_{max}}}$$

ex $$0.017035\text{s} = \sqrt{\frac{2 \cdot 39\text{kg·m}^2 \cdot (47.5^\circ - 10^\circ)}{\pi \cdot 56\text{Hz} \cdot 1000\text{W}}}$$

9) Damped Frequency of Oscillation in Power System Stability

Open Calculator

fx $$\omega_{df} = \omega_{fn} \cdot \sqrt{1 - (\xi)^2}$$

ex $$8.954887\text{Hz} = 9\text{Hz} \cdot \sqrt{1 - (0.1)^2}$$

10) Inertia Constant of Machine

Open Calculator

fx $$M = \frac{G \cdot H}{180 \cdot fs}$$

ex $$0.059091 = \frac{15 \cdot 39\text{kg·m}^2}{180 \cdot 55\text{Hz}}$$

11) Kinetic Energy of Rotor

Open Calculator

fx $$KE = \left(\frac{1}{2}\right) \cdot J \cdot \omega_s^2 \cdot 10^{-6}$$

ex $$0.000192\text{J} = \left(\frac{1}{2}\right) \cdot 6.0\text{kg·m}^2 \cdot (8\text{m/s})^2 \cdot 10^{-6}$$

12) Lossless Power Delivered in Synchronous Machine

Open Calculator

fx $$P_l = P_{max} \cdot \sin(\delta)$$

ex $$707.1068\text{W} = 1000\text{W} \cdot \sin(45^\circ)$$

13) Maximum Steady State Power Transfer

Open Calculator

fx $$P_{e,max} = \frac{\text{modulus}(E_g) \cdot \text{modulus}(V)}{X_s}$$

ex $$30.87719\text{V} = \frac{\text{modulus}(160\text{V}) \cdot \text{modulus}(11\text{V})}{57\Omega}$$

14) Moment of Inertia of Machine under Power System Stability

Open Calculator

fx $$M_i = J \cdot \left(\frac{2}{P}\right)^2 \cdot \omega_r \cdot 10^{-6}$$

ex $$0.000726\text{kg·m}^2 = 6.0\text{kg·m}^2 \cdot \left(\frac{2}{2}\right)^2 \cdot 121\text{m/s} \cdot 10^{-6}$$

15) Output Power of Generator under Power System Stability

Open Calculator

fx $$P_g = \frac{E_g \cdot V_t \cdot \sin(\zeta_{op})}{x_d}$$

ex $$0.096\text{W} = \frac{160\text{V} \cdot 3\text{V} \cdot \sin(90^\circ)}{5000\text{AT/Wb}}$$

16) Real Power of Generator under Power Angle Curve

Open Calculator

fx $$P_e = \frac{\text{modulus}(E_g) \cdot \text{modulus}(V)}{X_s} \cdot \sin(\delta)$$

ex $$21.83347\text{W} = \frac{\text{modulus}(160\text{V}) \cdot \text{modulus}(11\text{V})}{57\Omega} \cdot \sin(45^\circ)$$

17) Rotor Acceleration

Open Calculator

fx $$P_a = P_i - P_{ep}$$

ex $$100.1\text{W} = 200\text{W} - 99.9\text{W}$$

18) Speed of Synchronous Machine

Open Calculator

fx $$\omega_{es} = \left(\frac{P}{2}\right) \cdot \omega_r$$

ex $$121\text{m/s} = \left(\frac{2}{2}\right) \cdot 121\text{m/s}$$

19) Synchronous Power of Power Angle Curve

Open Calculator

fx $$P_{syn} = \frac{\text{modulus}(E_g) \cdot \text{modulus}(V)}{X_s} \cdot \cos(\delta)$$

ex $$21.83347\text{W} = \frac{\text{modulus}(160\text{V}) \cdot \text{modulus}(11\text{V})}{57\Omega} \cdot \cos(45^\circ)$$

20) Time Constant in Power System Stability

Open Calculator

fx $$T = \frac{2 \cdot H}{\pi \cdot \omega_{df} \cdot D}$$

ex $$0.110964\text{s} = \frac{2 \cdot 39\text{kg·m}^2}{\pi \cdot 8.95\text{Hz} \cdot 25\text{Ns/m}}$$

Variables Used

- **D** Damping Coefficient *(Newton Second per Meter)*
- E_g EMF of Generator *(Volt)*
- **f** Frequency *(Hertz)*
- **fs** Synchronous Frequency *(Hertz)*
- **G** Three Phase MVA Rating of Machine
- **H** Constant of Inertia *(Kilogram Square Meter)*
- I_p Phasor Current *(Ampere)*
- **J** Rotor Moment of Inertia *(Kilogram Square Meter)*
- **KE** Kinetic Energy of Rotor *(Joule)*
- **M** Inertia Constant of Machine
- M_i Moment of Inertia *(Kilogram Square Meter)*
- **P** Number of Machine Poles
- P_a Accelerating Power *(Watt)*
- P_e Real Power *(Watt)*
- $P_{e,max}$ Maximum Steady State Power Transfer *(Volt)*
- P_{ep} Electromagnetic Power *(Watt)*
- P_g Output Power of Generator *(Watt)*
- P_i Input Power *(Watt)*
- P_{inf} Active Power of Infinite Bus *(Watt)*
- P_l Lossless Power Delivered *(Watt)*
- P_{max} Maximum Power *(Watt)*
- P_{syn} Synchronous Power *(Watt)*

- **R** Resistance *(Ohm)*
- **S** Complex Power *(Volt Ampere)*
- **t** Time of Angular Displacement *(Second)*
- **T** Time Constant *(Second)*
- T_a Accelerating Torque *(Newton Meter)*
- t_c Clearing Time *(Second)*
- t_{cc} Critical Clearing Time *(Second)*
- T_e Electrical Torque *(Newton Meter)*
- T_m Mechanical Torque *(Newton Meter)*
- **V** Voltage of Infinite Bus *(Volt)*
- V_p Phasor Voltage *(Volt)*
- V_t Terminal Voltage *(Volt)*
- x_d Magnetic Reluctance *(Ampere-Turn per Weber)*
- X_s Synchronous Reactance *(Ohm)*
- δ Electrical Power Angle *(Degree)*
- δ_a Angular Displacement of Machine *(Radian)*
- δ_c Clearing Angle *(Radian)*
- δ_{cc} Critical Clearing Angle *(Degree)*
- δ_{max} Maximum Clearing Angle *(Degree)*
- δ_o Initial Power Angle *(Degree)*
- ζ_{op} Power Angle *(Degree)*
- θ_m Angular Displacement of Rotor *(Radian)*
- ξ Oscillation Constant
- ω_{df} Damping Frequency of Oscillation *(Hertz)*

- ω_{es} Speed of Synchronous Machine *(Meter per Second)*
- ω_{fn} Natural Frequency of Oscillation *(Hertz)*
- ω_{r} Rotor Speed of Synchronous Machine *(Meter per Second)*
- ω_{s} Synchronous Speed *(Meter per Second)*

Constants, Functions, Measurements used

- Constant: **pi**, 3.14159265358979323846264338327950288
  Archimedes' constant
- Function: **acos**, acos(Number)
  The inverse cosine function, is the inverse function of the cosine function. It is the function that takes a ratio as an input and returns the angle whose cosine is equal to that ratio.
- Function: **cos**, cos(Angle)
  Cosine of an angle is the ratio of the side adjacent to the angle to the hypotenuse of the triangle.
- Function: **modulus**, modulus
  Modulus of a number is the remainder when that number is divided by another number.
- Function: **sin**, sin(Angle)
  Sine is a trigonometric function that describes the ratio of the length of the opposite side of a right triangle to the length of the hypotenuse.
- Function: **sqrt**, sqrt(Number)
  A square root function is a function that takes a non-negative number as an input and returns the square root of the given input number.
- Measurement: **Time** in Second (s)
  Time Unit Conversion
- Measurement: **Electric Current** in Ampere (A)
  Electric Current Unit Conversion
- Measurement: **Speed** in Meter per Second (m/s)
  Speed Unit Conversion
- Measurement: **Energy** in Joule (J)
  Energy Unit Conversion

- Measurement: **Power** in Watt (W), Volt Ampere (VA)
  Power Unit Conversion
- Measurement: **Angle** in Radian (rad), Degree (°)
  Angle Unit Conversion
- Measurement: **Frequency** in Hertz (Hz)
  Frequency Unit Conversion
- Measurement: **Electric Resistance** in Ohm (Ω)
  Electric Resistance Unit Conversion
- Measurement: **Electric Potential** in Volt (V)
  Electric Potential Unit Conversion
- Measurement: **Torque** in Newton Meter (N*m)
  Torque Unit Conversion
- Measurement: **Moment of Inertia** in Kilogram Square Meter (kg·m²)
  Moment of Inertia Unit Conversion
- Measurement: **Damping Coefficient** in Newton Second per Meter (Ns/m)
  Damping Coefficient Unit Conversion
- Measurement: **Reluctance** in Ampere-Turn per Weber (AT/Wb)
  Reluctance Unit Conversion

Check other formula lists

- Overhead AC Supply Formulas
- Overhead DC Supply Formulas
- Power System Stability Formulas
- Underground AC Supply Formulas
- Underground DC Supply Formulas

Feel free to SHARE this document with your friends!

PDF Available in

English Spanish French German Russian Italian Portuguese Polish Dutch

3/11/2024 | 9:28:05 AM UTC

Please leave your feedback here...